



For the version without covering,
 please contact: sales@alorair.com



SPARE PARTS LIST
HEPA Max 770

| | | | | | | | |
|----|----------------------------|------------------|---|------------|-------------------------------|-----------------|-----------------|
| 29 | Overload protection switch | module | 1 | 16 | Air outlet dust rack | steel net | 1 |
| 28 | indicator lamp | module | 1 | 15 | Air outlet support | ABS | 1 |
| 27 | Timer | module | 1 | 14 | lower casing | LLDPE | 1 |
| 26 | Control Panel | sheet iron | 1 | 13 | Stainless steel spring buckle | stainless steel | 4 |
| 25 | Rotary knob | plastic | 1 | 12 | The differential joint | copper | 2 |
| 24 | Main Control Panel | PCB | 1 | 11 | The motor bracket | stainless steel | 1 |
| 23 | GFCI outlet | module | 1 | 10 | motor | stainless steel | 1 |
| 22 | capacitor clamp | sheet iron | 1 | 9 | Guide solar or lunar halo | ABS | 1 |
| 21 | pressure difference switch | plastic | 1 | 8 | Compound filter screen | module | 1 |
| 20 | capacitance | module | 1 | 7 | G3 filter | module | 1 |
| 19 | Electric control box | galvanized sheet | 1 | 6 | Cover Upper | LLDPE | 1 |
| 18 | protective ring | plastic | 2 | 5 | R type clamp | plastic | 1 |
| 17 | The power cord buckle | polyamides | 1 | 4 | foot pad | TPV | 12 |
| | | | | 3 | Power cord fastener | polyamides | 4 |
| | | | | 2 | bridle line | polyamides | 1 |
| | | | | 1 | dust cap | plastic | 1 |
| | | | | No. | Name | Material | Quantity |