


Restoration&Moisture&Ventilation




SPARE PARTS LIST

PureAiro HEPA Pro 970



For the version without covering,
please contact:
sales@alorair.com



NO.	NAME MODEL	MATERIAL	QUANTITY
1	Dust Cap	Plastic	1
2	Bridle Line	Polyamides	1
3	Power Cord Fastener	Polyamides	4
4	Foot Pad	TPV	12
5	R Type Clamp	Plastic	1
6	Cover Upper	Lidpe	1
7	G3 Filter	Module	1
8	Compound Filter Screen	Module	1
9	Uv Lamp	Module	1
10	Lamp Card Buckle	Stainless Steel	2
11	Guide Solar Or Lunar Halo	ABS	1
12	Motor	Stainless Steel	1
13	The Motor Bracket	Stainless Steel	1
14	The Differential Joint	Copper	2
15	Stainless Steel Spring Buckle	Stainless Steel	4
16	Lower Casing	LLDPE	1
17	Air Outlet Support	ABS	1
18	Air Outlet Dust Rack	Steel Net	1
19	The Power Cord Buckle	Polyamides	1
20	Protective Ring	Plastic	2
21	Electric Control Box	Galvanized Sheet	1
22	Ballast Assembly	Module	1
23	Capacitance	Module	1
24	Pressure Difference Switch	Plastic	1
25	Capacitor Clamp	Sheet Iron	1
26	Gfci Outlet	Module	1
27	Main Control Panel	PCB	1
28	Rotary Knob	Plastic	1
29	Control Panel	Sheet Iron	1
30	Timer	Module	1
31	Indicator Lamp	Module	1
32	Overload Protection Switch	Module	1