



For the version without covering,
please contact: sales@alorair.com

Restoration&Moisture&Ventilation



SPARE PARTS LIST
Cleanshield HEPA 550

25	bracket screw	M6*20	4	8	activated carbon filter	component	1
24	cover plate	galvanized sheet	1	7	HEPA filter	component	1
23	fan bracket	galvanized sheet	1	6	E sealing strip	PE	1
22	centrifugal fan	component	1	5	fixed block	component	8
21	handle	component	1	4	primary filter	component	1
20	rotary knob	component	1	3	front housing	LLDPE	1
19	warning light	115 60Hz 10A	1	2	dust cover sealing strip	component	1
18	double socket	115 60Hz 10A	1	1	dust cover	PE	1
17	power switch	115 60Hz 10A	1	No.	Name	Material	Quantity
				16	operation panel	galvanized sheet	1
				15	PCB	component	1
				14	air-out net rack	φ 3 steel wire	1
				13	back housing	LLDPE	1
				12	foot pad	rubber	8
				11	buckle	stainless steel	4
				10	foot pad	rubber	4
				9	back housing seal ring	115V 60Hz 10A	1